

West Virginia Child Labor Laws

Child Labor Hazardous Occupation Order #11

West Virginia Division of Labor
Wage & Hour Section

Child Labor Fact Sheet 4.11 - Chapter 21, Article 6, Section 2(a)(11) & §42CSR-9 4.23

Reference: Federal Regulation Title 29, Part 570, Subpart E - §570.62

(July 2016)

HAZARDOUS OCCUPATION ORDER #11

OCCUPATIONS INVOLVED IN THE OPERATION OF BAKERY MACHINES

(a) *Finding and declaration of fact.* The following occupations involved in the operation of power-driven bakery machines are particularly hazardous for the employment of minors between 16 and 18 years of age:

(1) The occupations of operating, assisting to operate, or setting up, adjusting, repairing, oiling, or cleaning any horizontal or vertical dough mixer; batter mixer; bread dividing, rounding, or molding machine; dough brake; dough sheeter; combination bread slicing and wrapping machine; or cake cutting band saw.

(2) The occupation of setting up or adjusting a cookie or cracker machine.

(b) *Exceptions.*

(1) This section shall not apply to the operation, including the setting up, adjusting, repairing, oiling and cleaning, of lightweight, small capacity, portable counter-top power-driven food mixers that are, or are comparable to, models intended for household use. For purposes of this exemption, a lightweight, small capacity mixer is one that is not hardwired into the establishment's power source, is equipped with a motor that operates at no more than $\frac{1}{2}$ horsepower, and is equipped with a bowl with a capacity of no more than five quarts. *Except*, this exception shall not apply when the mixer is used, with or without attachments, to process meat or poultry products as prohibited by §570.61(a)(4).

(2) This section shall not apply to the operation of pizza-dough rollers, a type of dough sheeter, that: have been constructed with safeguards contained in the basic design so as to prevent fingers, hands, or clothing from being caught in the in-running point of the rollers; have gears that are completely enclosed; and have micro switches that disengage the machinery if the backs or sides of the rollers are removed. This exception applies only when all the safeguards detailed in this paragraph are present on the machine, are operational, and have not been overridden. This exception does not apply to the setting up, adjusting, repairing, oiling or cleaning of such pizza-dough rollers.